



---

## Care information

---

KADECO honeycomb pleated blinds are resistant to dust and dirt because of the special coating that is applied to both sides. However, should you still wish to clean them, please follow the specific care instructions by referring to the cleaning symbols.

Mechanical parts of electrical and winding units must not come into contact with water! Never use abrasive or alkaline detergents to clean glass or window frames. We cannot accept any liability for fabric damage caused by condensation, detergents or insects soiling the fabric. Nor do we accept any liability for subsequent damage due to incorrect handling of our products.



### Brushing

Soiling (e.g. dust) can generally be removed with a soft clothes brush or carefully vacuumed off using a brush attachment.



### Damp cloth

To moist-wipe the honeycomb pleated blind, place it on a smooth surface. Wipe the honeycomb pleated blind carefully on both sides with a soft cloth that has been moistened with mild detergent.



### Cleaning bath

Move the honeycomb pleated blind around in a warm mild detergent solution (max. 30°C) for no more than 10 to 15 minutes. It is important to use a detergent with a particularly low concentration of surfactants (such as "Burti" for the German market). After immersing the fabric in the detergent, rinse it out with clean water, fold the fabric stack together again and press the water out. Hang the system up again whilst still damp and, throughout the day, keep alternately raising (so that the fabric can dry out completely) and lowering it (so that the folds are retained).

### Ironing

Important: Do not iron honeycomb pleated blinds!